

## PLM SERIES Mounting guide

	2400Pa load 2400Pa wind load 2400Pa snow load	5400Pa load 5400Pa wind load 3800Pa snow load
Mounting system	Use four Mounting holes	Use eight Mounting holes
Clamping system long frame attachment to the long frame	Use four clamps  Clamping Zone Frome module edge to 1/4 length ±50mm	Use six clamps
Clamping system long frame attachment to the short frame	Use four clamps on short frame  Clamping Zone Frome module edge to 1/4 length ±50mm	Use four clamps on short frame    Clamping Zone   Frome module edge to 1/4   length ±50mm
insertion system	Use insertion system on short frame	Use insertion system on short frame and two clamps at the center of each long frame  Use insertion system on long frame  Use insertion system on long frame